



Photo # 17 REMAINS OF RADIO



Photo # 18 RIGHT SIDE DASH




Photo # 19 FRONT FLOOR AND SEAT AREA



Photo # 20 DASH WIRING



Photo # 21 DASH WIRING



Photo # 22 DASH WIRING



Photo # 23 DASH WIRING



Photo # 24 FRONT DASH AND FLOOR




Photo # 25 ITEMS IN TRUNK



Photo # 26 ITEMS IN TRUNK




Photo # 27 ITEMS IN TRUNK




Photo # 28 ITEMS IN TRUNK




Photo # 29 ITEMS IN TRUNK




Photo # 30 ITEMS IN TRUNK



Photo # 31 RADIATOR AND COMPONENTS FOUND IN INTERIOR



Photo # 32 RADIATOR FAN MOTOR AND WIRING




Photo # 33 ENGINE COMPARTMENT COMPONENTS FOUND IN INTERIOR



Photo # 34 UNDERSIDE OF HOOD




Photo # 35 ENGINE COMPARTMENT



Photo # 36 LEFT SIDE OF ENGINE COMPARTMENT




Photo # 37 CENTER OF ENGINE COMPARTMENT




Photo # 38 RIGHT SIDE OF ENGINE COMPARTMENT




Photo # 35 ENGINE COMPARTMENT



Photo # 36 LEFT SIDE OF ENGINE COMPARTMENT




Photo # 37 CENTER OF ENGINE COMPARTMENT




Photo # 38 RIGHT SIDE OF ENGINE COMPARTMENT




Photo # 39 RIGHT REAR OF ENGINE COMPARTMENT



Photo # 40 BATTERY AND WIRING




Photo # 41 ELECTRICAL EXAMINATION




Photo # 42 REMAINS OF FUEL LINES



Photo # 43 REMAINS OF FUEL LINES




Photo # 44 OIL LEVEL




Photo # 45 REMAINS OF OIL FILLER CAP




Photo # 46 LEFT FRONT UNDERCARRIAGE



Photo # 47 LEFT FRONT UNDERCARRIAGE



Photo # 48 RIGHT FRONT UNDERCARRIAGE



Photo # 49 FRONT UNDERCARRIAGE



Photo # 50 UNDERCARRIAGE



Photo # 52 UNDERCARRIAGE



Photo # 53 UNDERCARRIAGE



Photo # 54 UNDERCARRIAGE



Photo # 55 UNDERCARRIAGE



Photo # 56 UNDERCARRIAGE